

# REPORT

## TRUESDAIL LABORATORIES, INC.



14201 FRANKLIN AVENUE  
TUSTIN, CALIFORNIA 92680  
AREA CODE 714 • 730-6239  
AREA CODE 213 • 225-1564  
CABLE: TRUELABS

CHEMISTS - MICROBIOLOGISTS - ENGINEERS  
RESEARCH - DEVELOPMENT - TESTING

CLIENT **Douglas Aircraft Company**  
Internal Mail Code 211-40  
3855 Lakewood Blvd.  
Long Beach, CA 90846  
SAMPLE Attn: Robert M. Tomko

DATE July 12, 1988  
RECEIVED June 21, 1988  
LABORATORY NO. 26811

INVESTIGATION **Monthly Storm Drain Inspection**  
Purchase Order Number T & M-23465-C


As requested by the CRWQCB for MPDES permit #'s  
CA0001406 & CA0001414


### RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on June 21, 1988, at the Douglas, Long Beach facility (003) and Torrance facilities. The discharge was tested for flow rate, pH and temperature. The results are as follows:

<u>Sample I.D.</u>	<u>Date</u>	<u>Time</u>	<u>Flow - gpd</u>	<u>Temp °F</u>	<u>pH Units</u>
Long Beach (003)	6/21/88	12:00	32,659	75°F	8.1
Torrance	6/21/88	10:45	3,230	70°F	7.8

Respectfully submitted,  
TRUESDAIL LABORATORIES, INC.

  
Luis Perez, Supervisor  
Industrial Waste



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.